## - Site Service Report -

June 8, 2009

IRD SO#: 10407? IRD Ref:

From: Ray Pollon

To: Shawn Brown, Bruce Myers, Darren Thiessen

Project Name: Jackson, TN

Project Location: 1-40

Service Date(s): January 04, 2008

Weather:

**Job Description:** Site ring, no-answer. Troubleshoot modem problem.

## **Work Completed:**

- Found site to have power and acceptable voltage on phone line (48VDC)
- Noted no TR light illuminated on phone prior to hard restart.
- Power cycled WIM/Modem
- Verified remote access via modem.
- Verified operation

## Work Remaining:

- Timer needs to be installed onsite
- Site log book need to be installed

<b>Parts</b>	Used:	
raits	USEU.	

Mileage / Travel Time:

Time Spent on Site:

Notes:

## **Action Items:**

Item	Action Required	Ownership
1.		